

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340

February 3, 1992

TO:

Minerals File

FROM:

Tony Gallegos, Reclamation Engineer 2011

RE:

Site Inspection, State Lease #1, John Harris, S/027/013, Millard County, Utah

Date of Inspection:

January 30, 1992

Conditions:

Sunny, cool, some snow drifts

Time of Inspection: 1635 - 1745

Participants:

Wayne Hedberg, Tony Gallegos, DOGM

This site and the other nearby Trilobite operations were inspected while in the area. The inspections were not planned and were cursory in nature. All sites are located on State Lands.

This site is across the drainage from the main access road. A truck and two persons were present at the site upon our arrival. The people were Ed and Shaun Harris. They informed us that they had been doing some work at their site and there was also someone working at the site further up the canyon. The disturbance at this site has grown slightly by the expansion of the waste dumps which showed signs of recent activity. Photographs were taken to compare with previous Division photos.

jb

cc:

Jerry Mansfield, State Lands

